



TO: Dick Coulombe
HID Global
611 Center Ridge Drive
Austin, TX 78753

FROM: Matthew Arnold on behalf of the FIPS 201 Evaluation Program

DATE: 5/2/2023

RE: Update of APL Approval Letter

Office of Management and Budget (OMB) issued M-19-17 that requires Federal Agencies to procure only qualified products and services listed on the GSA Approved Products List (APL) when implementing HSPD-12 into their environment. Procurement of approved products and services facilitates the government-wide objective of a federated and interoperable ICAM segment architecture. It ensures compliance, consistency, and alignment of commercially-available products and services with the requirements and functional needs of government ICAM implementers.

Accordingly, the FIPS 201 Evaluation Program (Program) is very pleased to inform you that the following product/service has passed testing against all applicable Testing Requirements. Please see the attached document that summarizes the specific parameters of the approval (e.g., product/service profile, what your product/service was tested with). Your product/service will now be listed on the APL, as shown below. If there are any errors in the listing information, please notify me within five (5) business days of receiving this letter.

Approval Authorization Letter

1 Category-Validation System (APL #10020)

1.1 APL Certification Number

- (APL#10020)
 - pivCLASS Registration Engine (Gallagher PIV Command Centre)
 - pivCLASS Registration Engine (MultiPACS)
 - pivCLASS MultiPACS Console
 - pivCLASS Certificate Manager
 - pivCLASS IDPublisher
 - pivCLASS MultiPACS Connector for Gallagher Command Centre

1.2 Product/Service Information

Organization Name:	HID Global
Name of Product or Service:	pivCLASS Registration Engine (Gallagher PIV Command Centre)
Part Number:	PVCP-D/S-07-00
Hardware Version:	
Software Version:	5.24.0.0
Firmware Version:	

Organization Name:	HID Global
Name of Product or Service:	pivCLASS Registration Engine (MultiPACS)
Part Number:	PVCP-D/S-00-00
Hardware Version:	
Software Version:	5.24.0.0
Firmware Version:	

Organization Name:	HID Global
Name of Product or Service:	pivCLASS MultiPACS Console
Part Number:	PVC-MPX-CNSL
Hardware Version:	
Software Version:	5.24.0.0
Firmware Version:	

Organization Name:	HID Global
Name of Product or Service:	pivCLASS Certificate Manager
Part Number:	PVC-CM
Hardware Version:	
Software Version:	5.24.0.0
Firmware Version:	

Organization Name:	HID Global
Name of Product or Service:	pivCLASS IDPublisher
Part Number:	PVC-IDPUBUNL
Hardware Version:	
Software Version:	5.24.0.0
Firmware Version:	

Organization Name:	HID Global
Name of Product or Service:	pivCLASS MultiPACS connector for Gallagher Command Centre
Part Number:	PVC-MPX-CNX-07-00
Hardware Version:	
Software Version:	5.24.0.0
Firmware Version:	

1.3 Document History

Status	Date	Comments
Approved	7/8/2014	Final Approval Date for APL# 10020 Software Version HID pivCLASS 1.2.247.0
Update	7/7/2015	Final Approval Date for Software Version Update to HID pivCLASS 1.2.285.0
Update	4/13/2016	Final Approval Date for Software Version Update to HID pivCLASS 1.2.297.0
Update	1/31/2017	Final Approval Date for Software Version Update to HID pivCLASS 1.2.304.0
Update	3/17/2017	Final Approval Date for Software Version Downgrade to HID pivCLASS 1.3.3.0, added MultiPACS components
Update	4/25/2017	Final Approval Date for Integration with HID pivCLASS 1.3.3.0 MultiPACS Components
Update	9/7/2018	Final Approval Date for Integration with HID pivCLASS 1.4.10.0 MultiPACS Components with Gallagher Command Centre 7.80. Added Veridt Stealth Bio reader to Gallagher Command Centre PACS Infrastructure.

Update	11/14/2018	Final Approval Date for Integration with HID pivCLASS 5.6.2 MultiPACS Components with Gallagher Command Centre 7.90.
Update	06/07/2019	Final Approval Date for Integration with HID pivCLASS 5.10.0.1 MultiPACS Components with Gallagher Command Centre 8.0.
Update	12/5/2019	Update software for Gallagher Command Center 8.10 and HID pivCLASS 5.10.0.1
Update	5/13/2020	Update Gallagher Command Centre 8.20 and HID pivCLASS 5.11.0.0
Update	7/16/2021	Update Gallagher Command Centre 8.40 and HID pivCLASS 5.16.0.0 and addition of Allegion readers
Correction	7/22/2021	Correction of Allegion reader series.
Update	5/2/2023	Updated HID pivCLASS 5.24.0.0 software version numbers.

1.4 Restrictions:

This product has been tested and approved as a component of a fully compliant FICAM Solution. The end-to-end solution components used to test the FICAM compliance of the approved solution are listed below.

- PACS Infrastructure (**APL# 10019**)
 - Gallagher PIV Command Centre,
 - Controller 6000 High Spec - PIV,
 - Controller 6000 High Spec 2 Door - PIV,

- PIV Reader
 - Gallagher T10 PIV Reader, (**APL# 10021**)
 - Gallagher T11 PIV Reader, (**APL# 10022**)
 - Gallagher T11 PIV Reader - Multi-Tech, (**APL# 10023**)
 - Gallagher T20 PIV Reader, (**APL# 10038**)
 - Gallagher T20 PIV Reader - Multi-Tech, (**APL# 10039**)
 - Gallagher T21 PIV Reader, (**APL# 10099**)
 - Gallagher T21 PIV Reader, (**APL# 10143**)

- o Gallagher T21 PIV Reader - Multi-Tech, (APL# 10100)
- o Gallagher T15 PIV Reader, (APL# 10101)
- o Gallagher T15 PIV Reader – Multi-Tech, (APL# 10102)
- o Veridt Bio Dual Contact/Contactless Keypad Reader – (APL# 10092)
- o Allegion Schlage AD-302 FIPS 201-2 (APL #10133)

Approval of the above product/service indicates your cooperation with the Program and successful testing against a rigorous, comprehensive set of functional requirements derived from government-wide specifications. Testing included positive and negative test cases and threat vectors.

Given the strategic government-wide importance of the APL, the scope and extent of testing performed on your product/service, and the rigor of that testing, the Program would like to acknowledge the noteworthiness of the approval and listing. Your product/service will now be available to all Federal Agencies for procurement.

Please note that continued listing on the APL requires ongoing conformance to all applicable requirements, including requirements added or amended over time. A listed product/service can become non-conformant for various reasons, including but not limited to:

- Failure to pass testing against new and revised requirements before the effective date of the new/revised requirements.
- Problems discovered in your listed product/service (or class of product/service) are not addressed within the time frames specified by the Program.

Refer to applicable Agreements and Program documents for details regarding ongoing compliance, including severity levels and remediation time frames. Listed products and services that fall out of conformance will be removed from the APL and added to the Removed Products List (RPL).

If you have any questions, please feel free to contact me.

Matthew Arnold
GSA OGP
(703) 254-6750 (Cell)
Matthew.Arnold@gsa.gov