



TO: Dick Coulombe
HID Global
611 Center Ridge Drive
Austin, TX 78753

FROM: Chi Hickey on behalf of the FIPS 201 Evaluation Program

DATE: 3/24/2018

RE: **Updated Approval of Products/Services for Listing on the GSA APL**

Office of Management and Budget (OMB) issued M-06-18 that requires Federal Agencies to procure only qualified products and services listed on the GSA Approved Products List (APL) when implementing HSPD-12 into their environment. Procurement of approved products and services facilitates the government-wide objective of a federated and interoperable ICAM segment architecture, and ensures compliance, consistency and alignment of commercially-available products and services with the requirements and functional needs of government ICAM implementer.

Accordingly, the FIPS 201 Evaluation Program (Program) is very pleased to inform you that the following product/service has passed testing against all applicable Testing Requirements. Please see the attached document that summarizes the specific parameters of the approval (e.g., product/service profile, what your product/service was tested with). Your product/service will now be listed on the APL as shown below. If there are any errors in the listing information, please notify me within five (5) business days of receiving this letter.

Approval Authorization Letter

1 Category-Validation System

- (APL#10010)
 - pivCLASS Registration Engine (Brivo OnSite Server)
 - pivCLASS Registration Engine (MultiPACS)
 - pivCLASS Certificate Manager
 - pivCLASS Reader Services
 - pivCLASS IDPublisher
 - pivCLASS MultiPACS Console
 - pivCLASS MultiPACS connector for Brivo OnSite Server
 - pivCLASS Authentication Module

1.1 Product/Service Information

| | |
|------------------------------------|--|
| Organization Name: | HID Global |
| Name of Product or Service: | pivCLASS Registration Engine (Brivo OnSite Server) |
| Part Number: | PVCP-D/S 03-00 |
| Hardware Version: | |
| Software Version: | 1.4.10.0 |
| Firmware Version: | |

| | |
|------------------------------------|--|
| Organization Name: | HID Global |
| Name of Product or Service: | pivCLASS Registration Engine (MultiPACS) |
| Part Number: | PVCP-D/S-00-00 |
| Hardware Version: | |
| Software Version: | 1.4.10.0 |
| Firmware Version: | |

| | |
|------------------------------------|------------------------------|
| Organization Name: | HID Global |
| Name of Product or Service: | pivCLASS Certificate Manager |
| Part Number: | PVC-CM |
| Hardware Version: | |
| Software Version: | 1.4.10.0 |
| Firmware Version: | |

| | |
|------------------------------------|--------------------------|
| Organization Name: | HID Global |
| Name of Product or Service: | pivCLASS Reader Services |
| Part Number: | PVC-FXRDR |

| | |
|--------------------------|----------|
| Hardware Version: | |
| Software Version: | 1.4.10.0 |
| Firmware Version: | |

| | |
|------------------------------------|----------------------|
| Organization Name: | HID Global |
| Name of Product or Service: | pivCLASS IDPublisher |
| Part Number: | PVC-IDPUBUNL |
| Hardware Version: | |
| Software Version: | 1.4.10.0 |
| Firmware Version: | |

| | |
|------------------------------------|----------------------------|
| Organization Name: | HID Global |
| Name of Product or Service: | pivCLASS MultiPACS Console |
| Part Number: | PVC-MPX-CNSL |
| Hardware Version: | |
| Software Version: | 1.4.10.0 |
| Firmware Version: | |

| | |
|------------------------------------|--|
| Organization Name: | HID Global |
| Name of Product or Service: | pivCLASS MultiPACS connector for Brivo OnSite Server |
| Part Number: | PVC-MPX-CNX-03-00 |
| Hardware Version: | |
| Software Version: | 1.4.10.0 |
| Firmware Version: | |

| | |
|------------------------------------|--------------------------------|
| Organization Name: | HID Global |
| Name of Product or Service: | pivCLASS Authentication Module |
| Part Number: | 91000ABNNN |
| Hardware Version: | |
| Software Version: | |
| Firmware Version: | 5.4.136 |

1.2 Document History

| Status | Date | Comments |
|----------|------------|--|
| Approved | 10/25/2013 | Final Approval Date for APL# 10010 Software Version 1.2.238.0 |
| Update | 7/7/2015 | Update to Approval letter to add RKCLB40 Reader (APL #10052) and Upgrade Software Version to 1.2.285.0 |

| | | |
|--------|------------|--|
| Update | 10/8/2015 | Update Product Names from Brivo Aparato to Brivo OnSite Server |
| Update | 12/15/2015 | Final Approval Date of Upgrade Firmware on pivCLASS Authentication Module to Version 5.1.8 |
| Update | 2/1/2016 | Final Approval Date of Upgrade Software Version to 1.2.297.0, update Brivo's Product Names |
| Update | 3/17/2017 | Final Approval Date of Brivo OnSite Server Software Version 3.2.3 with HID pivCLASS Validation System Version 1.2.302.0, Firmware Version on pivCLASS Authentication Module to 5.1.13. |
| Update | 5/16/2017 | Final Approval Date of HID pivCLASS Validation System software update to Release 1.3.4.0, with HID pivCLASS 1.3.4.0 and PAM firmware version 5.3.67 with Brivo OnSite Server Software Version 3.2.3. |
| Update | 5/26/2017 | Approval of Brivo OnSite Server PACS Infrastructure software update to version 3.3.4, with HID pivCLASS 1.3.4.0 and PAM firmware version 5.3.67. |
| Update | 2/27/2018 | Approval of Brivo OnSite Server PACS Infrastructure software update to version 3.4.2 with B-ACS6000-A control panel, with HID pivCLASS 1.3.4.0 and PAM firmware version 5.3.71. |
| Update | 3/24/2018 | Approval of HID pivCLASS 1.4.10.0 and PAM firmware version 5.4.136 |

1.3 Restrictions:

This product has been tested and approved as a component of a fully compliant FICAM Solution. The end to end solution components used to test the FICAM compliance of the approved solution are listed below.

- PACS Infrastructure: (**APL# 10009**)
 - Brivo OnSite Server, Release 3.4.2
 - Brivo B-ACS5000-A: Control Panel, Firmware Release 3.4.2
 - Brivo B-ACS5000-DB: Dual Reader Expansion Board, Firmware Release 3.4.2
 - Brivo B-ACS6000-A: Control Panel, Firmware Release 3.4.2
 - Brivo B-ACS6000-DB: Dual Reader Expansion Board, Firmware Release 3.4.2
 - Brivo B-ACS300-A: IP door controller, Firmware Release 3.4.2
 - Brivo IP Door Controller FIPS 140-2 module license, Firmware Release 3.4.2
- PIV Reader
 - pivCLASS RP40 Contactless Reader VAS0300 Rev. B.1 (**APL#10003**)
 - pivCLASS RK40 Contactless Reader + PIN VAS0300 Rev. B.1 (**APL# 10004**)
 - pivCLASS RPK40 Contactless Reader + PIN VAS0300 Rev. B.1 (**APL# 10005**)

- pivCLASS R40 Contactless Reader VAS0300 Rev. B.1 (**APL# 10006**)
- pivCLASS RKCL40 Contact/Contactless Reader with PIN VAS0300 Rev. B.1 (**APL# 10007**)
- pivCLASS RPKCL40 Contact/Contactless Reader with PIN VAS0300 Rev. B.1 VAS0300 Rev. B.1 (**APL# 10008**)
- pivCLASS RPKCLB40 Contact/Contactless Reader with PIN & BIO VAS0300 Rev. B.1 (**APL# 10026**)
- pivCLASS RKCLB40 Contact/Contactless Reader with PIN & BIO VAS0300 Rev. B.1 (**APL# 10052**)
- pivCLASS R10 Contactless Reader Rev. B.1 (**APL# 10085**)

Approval of the above product/service indicates your cooperation with the Program and successful testing against a rigorous, comprehensive set of functional requirements derived from government-wide specifications. Testing included positive and negative test cases, and threat vectors.

Given the strategic government-wide importance of the APL, the scope and extent of testing performed on your product/service and the rigor of that testing, the Program would like to acknowledge the noteworthiness of the approval and listing. Your product/service will now be available to all Federal Agencies for procurement.

Please note that continued listing on the APL requires ongoing conformance to all applicable requirements, including requirements added or amended over time. A listed product/service can become non-conformant for various reasons including but not limited to:

- Failure to pass testing against new and revised requirements before the effective date of the new/revised requirements.
- Problems discovered in your listed product/service (or class of product/service) are not addressed within time frames specified by the Program.

Refer to applicable Agreements and Program documents for specific details regarding ongoing compliance including severity levels and remediation time frames. Listed products and services that fall out of conformance will be removed from the APL and added to the Removed Products List (RPL).

If you have any questions, please feel free to contact me.

Sincerely,

Chi Hickey
GSA OGP
202-501-1881 (desk)
Chi.Hickey@gsa.gov